


IMAGE TRAIN FOR QSI500


Adapters required for the CDK17 and CDK20



QSI500 WSG Body	8.81 remaining BF	
3.5" Focuser (racked in)	3	5.81
Focus position (0 to 1.3")	0.51	5.3
3.5" to SecureFit, 2.1" - 200361-2	2.1	3.2
SecureFit 1/2" Spacer - 200377	0	3.2
CCD Adapter - 200397	0.25	2.95
CCD Adapter for QSI WSG - 600331	0.8	2.15
QSI500, WSG Body with no cover	1.75	0.4

Adapters required for the CDK12.5

Distance to Focuser Mounting Surface 10.45



QSI500 WSG Body	10.45 remaining BF	
3.5" Focuser (racked in)	3.25	7.2
Focus position (0 to 1.3")	0.4	6.8
2.75" to SecureFit, 2.1" - 125357-2	3.5	3.3
SecureFit 1/2" Spacer - 200377	0.5	2.8
SecureFit 1/2" Spacer - 200397	0.25	2.55
CCD Adapter for STQSI - 600331	0.8	1.75
QSI500, WSG Body with no cover	1.75	0